

March 14 1891

I commenced Survey of Section 31 Town 7 North, Range 6 West.

E F Cox
County Surveyor.

O B Winters } Chainmen
W J Hubbard }

John O'Connor JP Witness

Advertised 3 times
Linton Call
$2.00
Henry Switz
W H Deckard

COURSE.	DISTANCE.	REMARKS.	
	From S.E. Cor		
West	10.00	Marsh. Squibb trees grow. North of stake.	
	40.38	S¼	
	85.18	S.W. Cor Left 32½ Links	3°25"
	from S.E. Cor		
North.	40.31	E¼ Cor Set & Stone. Qt	
	60 28½	E¼ N.E. Set Cor	3°30"
	80.26	N.W. Cor. & Set Cor.	
	From N. &		
West	40.08	W¼	3°30"
	85.07	Range line	

Traced line on Squibbs Swamp Survey of fraction in SE ¼. Could not make Chain & angles come out. Unable to Make out his Var of needle. Area inclosed by Thirds. he Run his line at an angle from East line of Section. in doing this. I Came out 4 links east of Cor. Set. but Chaining was 61 links too long on last Angle. did not Establish any bearing on this line.

Corners Established.	Monument.	Bearing Trees.	Diameter in Inches.	Course.	Links Distant.
Plat 1870					
1870 16	Stake	Willow	8	S 20°-15 E	74
		"	6	N 4°-45" E	42
"	Stone	"	20	N 76¼ W	20
		"	8	N 72¼ E	48½
" 11	Stone	Stone	W	E	50
		"	W	N	50
" A	Squibbs Cor Stone	Black Walnut	10	S 64½ E	114
10 ch. W. SE Cor.		White Oak	18	N 48 W	105
" 21	Stone	Stone	W	N ~~50~~	50
		"	W	S	50